| 2021/22 Capital Programme - HRA  |   |           |   |
|--|---|-----------|---|
| Project & Category   | Description   | Estimate  | Notes   |
|  |   | £         |   |
| Retentions & minor carry-<br>forward   | Retentions and minor carry<br>forward from projects in<br>progress up to 31 March<br>2021   | 40,000    |   |
| Modern Homes   |   |           |   |
| Kitchen, bathroom and<br>electrical upgrades   | Renew kitchens,<br>bathrooms and electrical<br>installations where existing<br>are life expired and in poor<br>condition                    | 1,650,000 | Cyclical modernisation to<br>maintain decent housing<br>and modern<br>facilities.Replacements<br>scheduled for 2021/22<br>from our asset<br>management data.<br>Properties pre-surveyed to<br>ensure asset requires<br>replacement. |
| Void Properties -<br>refurbishment   | Refurbishment of<br>individual properties to<br>enable them to be relet   | 660,000   | Estimated allowance for<br>40 major void properties<br>requiring extensive work<br>throughout based on<br>current demand  |
| Structural   |   |           |   |
| Structural works - various<br>properties   | Structural works including<br>structural investigation and<br>remedial works due to<br>foundation subsidence or<br>other structural issues. | 420,000   | Repairs and major works<br>to structurally defective<br>properties which includes<br>underpinning and decant<br>costs where necessary<br>due the extent of works<br>required  |
| Doors & Windows  |   |           |   |
| Renewal of doors and door<br>entry systems to three storey<br>flats:<br>29-39 Rye Close<br>41-51 Rye Close<br>193-203 Park Barn Drive<br>221-231 Park Barn Drive | Replacement of external<br>main entrance doors and<br>side screens and<br>installation of new door<br>entry systems                         | 30,000    | Doors life expired.<br>Additional security wil be<br>provided by door entry<br>systems  |
| Replacement of windows and doors   | Replace life expired and<br>unserviceable windows &<br>doors with double glazed<br>UPVC   | 355,000   | Includes<br>Palmers Lodge - 28 flats<br>Collens Field - 8 houses<br>Friars Croft - 12 flats   |

| Roof Renewal   |  |         |  |
|--|--|---------|--|
| Pitched roof replacement<br>including chimneys, fascias,<br>soffits & rainwater<br>gutters/downpipes | Renew life expired roof<br>coverings and associated<br>works   | 305,000 | Various properties<br>including -<br>Georgelands (flats)<br>Burnt Common Cottages<br>(3)<br>Send Rd (1)<br>Quarry Rd (5)<br>Rickford Hill (6)<br>Thatchers Lane (5)                |
| External Wall Insulation   |  |         |  |
| External wall insulation<br>system to solid wall properties  | Provision of external wall<br>insulation to solid wall<br>properties to address poor<br>thermal insulation (year 3<br>of 4 year programme) | 332,000 | 2021/22 programme<br>mainly for "Swedish style"<br>properties with single skin<br>external walls - Glebe<br>Cottages (6 no) and<br>masonry built properties in<br>Stag Hill (4 no) |
| Mechanical & Electrical  |  |         |  |
| Central heating boiler<br>upgrades.<br>Various locations   | Upgrading existing central<br>heating installations with<br>high efficiency systems  | 500,000 | Annual programme of<br>domestic gas boiler<br>replacement  |
| Domestic Air Source Heat<br>Pump heating systems<br>Various locations                                | Replacement of aging<br>electric heating systems<br>with high efficiency air<br>source heat pump central<br>heating systems                | 100,000 | Budget allows for<br>installations in void<br>property where previous<br>tenant has declined<br>system   |
| Lift refurbishment.  | Continuation of phased<br>programme to replace<br>obsolete lift controllers  | 50,000  | Upgrade 1 No lift controller<br>at Bedford House (year 3<br>of 5 year programme)<br>plus door closers on all<br>lifts (following insurance<br>recommendations)                     |
| Lift replacement   | St Marthas Court - stairlift<br>installaton  | 50,000  | 4 no stairlifts which<br>provide an access<br>contingency when main<br>lifts have failed or are out<br>of use  |

| Lift replacement                                    | Friary House - replace lift<br>controller and associated<br>works   | 35,000  | Replacement of life<br>expired lift components   |
|---|---|---------|--|
| CCTV  | Installation of CCTV at St<br>Marthas Court, St Martins<br>Court, Millmead Court and<br>Tarragon Court                        | 20,000  | Security provision to<br>supported housing<br>schemes with part time on<br>site management   |
| Electrical testing and smoke<br>detectors           | Electrical testing including<br>remedial work and wired in<br>smoke detector installation<br>where required                   | 435,000 | Includes testing &<br>associated repairs to<br>communal areas in blocks<br>of flats. Start of rolling<br>annual programme  |
| General   |   |         |  |
| Replacement of external canopies to blocks of flats | Phased replacement<br>programme of defective<br>canopies to block entrance<br>doors with lightweight grp<br>canopies          | 90,000  | Phase 1 - 2021/22  |
| Asbestos Removal - Hazel<br>Court                   | Removal, disposal and<br>replacement of ceiling<br>beneath tank room under<br>fully controlled asbestos<br>removal conditions | 20,000  | Required to ensure safe<br>tanks inspection &<br>contractor access.<br>Temporary protection<br>currently in place but long<br>term solution required.                  |
| Garage forecourt resurfacing<br>programme           | Resurfacing of forecourt<br>areas to garage blocks<br>where existing surface in<br>poor condition.                            | 100,000 | Various sites -<br>continuation of rolling<br>annual planned<br>maintenance programme.<br>Concentrating on highest<br>use sites in high density<br>residential estates |

| 35 & 35 A The Mount         | Repairs to the external<br>fabric of listed block<br>comprising two leasehold<br>flats. Recommendation by<br>independent survey. | 40,000    | Remedial works to include<br>the following : repair roof<br>coverings, chimney<br>stacks, high level joinery,<br>windows and replace<br>vertical tile hangings.<br>Leasehold full cost<br>recoverable. |
|-----------------------------|--|-----------|--|
| Resurfacing of Access Roads | Resurfacing of access<br>roads at Mundays<br>Borough, Riverside and<br>Wodehouse Place   | 130,000   | Works will include<br>improvements to access<br>road, part of car park and<br>bin stores at Wodehouse<br>Place   |
| Condition Appraisals        | Annual programme of<br>condition appraisal surveys   | 50,000    | Annual programme budget<br>allowance   |
| Fire protection works       | Prioritised repair non-<br>urgent remedial works<br>comprising of containment,<br>doors<br>upgrades/replacement,<br>signage, etc | 150,000   |  |
| Mobility Scooter Enclosures | Purchase of additional<br>mobile scooter enclosures<br>for installation on bases<br>prepared in 2020/21.                         | 100,000   | Dray Court,<br>Japonica Court,<br>St Marthas Court<br>Works to address Fire<br>Risk Assessment<br>recommendation to<br>prevent obstruction.  |
| Condition Appraisal works   | Prioritised repair plus non-<br>urgent remedial works<br>recommended by<br>Condition appraisal<br>assessment                     | 150,000   |  |
|                             | Sub Total  | 5,812,000 |  |

| Other Capital                             |   |           |  |
|---|---|-----------|--|
| Environmental improvements                | General environmental<br>improvements at sites to<br>be agreed & subject to<br>resident consultation. | 50,000    |  |
| Disabled adaptations<br>Various locations | Works to alter, adapt<br>Council owned dwellings<br>for the benefit of people<br>with disability.     | 650,000   |  |
| Software systems                          | Provision to upgrade<br>essential business<br>software  | 30,000    |  |
| Programme support.                        | Programme support &<br>development to support<br>HRA Business Plan                                    | 40,000    |  |
|   | Total   | 6,582,000 |  |