

Appendix 3: Riverside Nature Reserve Photos

Riverside LNR

Boardwalk to be replaced



Boardwalk to be replaced

Regular vandalism



Typical occurrence of breakages



Surfaces and seating to be improved to meet higher accessibility standards



Circular route to be made more accessible at ditch crossings



Access to car park to be improved



Proposed installation of sluices to manage water level

